NEW-TECH FLOOR SYSTEMS REALIZE

WENCO® REVIVE[™] floor finish restorer as a regular part of propane and other high speed floor maintenance programs will greatly reduce labor and provide outstanding results. A one step product, use this formulation as a cleaner and restorer by mopping on and burnishing with a high speed machine or use through an automatic scrubber.

- Repairs scuffs and scratches, restores gloss.
- Compatible with most floor finishes.
- Reduces labor cost.
- For propane and other high speed equipment.

DIRECTIONS FOR USE READ THE ENTIRE LABEL BEFORE USING THIS PRODUCT.

MOP AND BURNISH METHOD

- 1. Dust mop floors to remove surface dirt and grit.
- 2. Add 2 ounces of **REVIVE™** per gallon of water (1:64) in a clean mop bucket.
- 3. Damp mop floor with solution, uniformly applying a thin coat.
- 4. Let floor dry thoroughly, burnish floor with a high speed floor machine and a soft polishing pad.

AUTOMATIC SCRUBBER METHOD

- 1. Dust mop floors to remove dirt and grit.
- Fill scrubber solution tank with water and add **REVIVE™**, 4 ounces per gallon of water (1:32).
- 3. Scrub the floor picking up solution as cleaning and detail mop any trails that are left behind from machine.
- 4. Let floor dry thoroughly and burnish with propane or other high speed floor equipment.

TECHNICAL PROPERTIES

Fe was	L factorial
Form	
Color	
Fragrance	Lemon
pH	8.0 - 9.0
Specific Gravity @75°F	
Density @ 75°F	8.48 lbs Per Gallon
Flash Point	None
Freeze/Thaw	3 Cycles
Gloss	Exceptional

AVAILABLE SIZES



- 5 Gallon Pail 100% Recyclable
- **55 Gallon Drum** Reconditioned, Reused



COMPANY





(800) 929-2141 • www.walterenelson.com

